



Industrial Hygiene • Air Quality • Lead & Asbestos • Training • Health & Safety

LIMITED ASBESTOS INSPECTION REPORT

Conducted at:

SHUEY ELEMENTARY SCHOOL
PAINTING PROJECT
8472 EAST WELLS STREET
ROSEMEAD, CALIFORNIA 91770

Prepared for:


MR. HAROLD SULLINS
ASSISTANT SUPERINTENDENT
ROSEMEAD SCHOOL DISTRICT
3907 ROSEMEAD BOULEVARD, SUITE 220
ROSEMEAD, CALIFORNIA 91770

Prepared by:

EXECUTIVE ENVIRONMENTAL
310 EAST FOOTHILL BOULEVARD, SUITE 200
ARCADIA, CALIFORNIA 91006

Project Number EE 21-Z0046-0066
July 23, 2021

Report assembled by:


Yesenia G. Galeana
Technical Report Writer
Executive Environmental

Report generated/reviewed by:



Tim Galeana, CLP # 3732
Senior Project Manager
Executive Environmental

TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY
- II. SAMPLING METHODOLOGY
- III. SAMPLE ANALYSIS
- IV. FINDINGS
- V. CONCLUSIONS/RECOMMENDATIONS
- VI. DISCLAIMER/REPORT LIMITATIONS

APPENDICES

APPENDIX A – LABORATORY ANALYSIS REPORT

APPENDIX B – SAMPLE LOCATIONS DRAWINGS

APPENDIX C – STAFF CERTIFICATION

LIMITED ASBESTOS INSPECTION REPORT

Project Number: EE 21-Z0046-0066

Client: Rosemead School District
3907 Rosemead Boulevard, Suite 220
Rosemead, California 91770

Site Location: Shuey Elementary School
Painting Project
8472 East Wells Street
Rosemead, California 91770

Site Use: School Property

Contact Person: Mr. Harold Sullins
Assistant Superintendent
Phone: (626) 312-2900

Inspection Date: May 18, 24 and 25, 2021

Inspected By: Mr. Rhys Kuzmic
Certified Asbestos Consultant, # 09-4586

Report Assembled By: Ms. Yesenia G. Galeana
Technical Report Writer

Report Generated/Reviewed By: Mr. Tim Galeana
Certified Asbestos Consultant, # 98-2470

I. EXECUTIVE SUMMARY

Executive Environmental (EE) provided the services of a Certified Asbestos Consultant to conduct a limited asbestos inspection of the permanent buildings, portables and covered walkways at Shuey Elementary School located at 8472 East Wells Street, Rosemead, California. The inspection was conducted as a precursor to the upcoming exterior painting project. Materials suspected of containing asbestos were sampled and analyzed for the presence of asbestos. No Asbestos-Containing Materials (ACM) were identified during this inspection. *This is considered to be a limited inspection. Inspection was limited to exterior materials anticipated to be impacted by the exterior painting project.*

II. SAMPLING METHODOLOGY

A visual inspection of the exterior of the permanent buildings, portables and covered walkways at Shuey Elementary School was conducted prior to the collection of any bulk samples. The visual inspection was conducted to identify and record the location and condition of the materials to be sampled. Following the visual inspection, bulk material samples of the identified suspect asbestos-containing building materials were collected.

The materials were categorized into homogeneous groupings, and each sample was assigned a unique sample number and placed into a sealed container.

Upon completion of the bulk sample collection, a chain of custody was prepared and the samples were delivered to the laboratory for analysis. AmeriSci of Carson, CA, and LA Testing of South Pasadena, CA analyzed the samples using Polarized Light Microscopy (PLM). AmeriSci is an accredited participant in the National Voluntary Laboratory Accreditation Program (NVLAP), No. 200346-0. LA Testing is an accredited participant in the National Voluntary Laboratory Accreditation Program (NVLAP), No. 200232-0, and is also accredited by the American Industrial Hygiene Association (AIHA), No. 102814. The principles described in the current Environmental Protection Agency (EPA) 600 method were used in the preparation and analysis of the bulk samples.

Note: Inaccessible suspect asbestos materials may be located within sealed ceilings, walls, or floors; or within wall cavities, interstitials, shafts, etc. Suspect asbestos materials located in these areas must be sampled prior to any activities that might cause them to be disturbed.

III. SAMPLE ANALYSIS

Sixty-six (66) samples were collected during this inspection. The laboratory analysis results are identified in the following table. Materials determined not to contain asbestos are listed as "No Asbestos Detected" (NAD).

Any material found to contain more than 1% of a known asbestos substance is considered to be an asbestos-containing material (ACM). Materials falling within this category are controlled and must be handled in accordance with the California Occupational Safety & Health Administration (Cal/OSHA), EPA, and South Coast Air Quality Management District (SCAQMD) regulations.

In addition, materials which are characterized as non-ACM by EPA or other local regulatory agencies may fall within the regulatory standards of Cal/OSHA, which further regulates any materials found to contain more than 1/10 of 1%, but 1% or less, of a known asbestos substance as asbestos-containing construction materials (ACCMs). Impacting or handling ACCMs requires special employer registration, documentation, training, and personal protective equipment. When a material is to be impacted, the National Emission Standards for Hazardous Air Pollutants (NESHAPs) regulations require further testing for materials that fall within this category.

The PLM analytical protocol requires each layer of the sample to be analyzed separately. The quantity of analyses will vary based on the number of layers in a sample and whether a "positive stop" is employed. When one sample of a homogeneous area is positive, the remainder of the samples need not be analyzed because the entire homogeneous area must be considered positive.

**Sampling results begin on the next page.
The remainder of this page is blank.**

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^A	Type ^B	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Administration/Classroom Building (Rooms 1 thru 4)^C										
1	Stucco	Throughout exterior walls and breezeway ceiling	6,000 Square Feet	G	Surf.	No	<1	2105180066RK-01	West wall	NAD ^D
								2105180066RK-02	South wall of Admin. Bldg.	NAD
								2105180066RK-03	South wall of Rooms 1 and 2	NAD
								2105180066RK-04	East wall	NAD
								2105180066RK-05	North wall of Admin. Bldg.	NAD
								2105180066RK-06	West wall of Breezeway	NAD
								2105180066RK-07	Southwest ceiling of Breezeway	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

^A G = Good; D = Damaged; SD = Severely Damaged

^B Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^C NOTE: 1) Wood overhangs. 2) No window putty.

^D NAD = No Asbestos Detected.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^E	Type ^F	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Classroom Building (Rooms 6 thru 12)^G										
2	Stucco	Throughout exterior walls, overhang and breezeway ceiling	5,000 Square Feet	G	Surf.	No	<1	2105180066RK-08	West wall	NAD ^H
								2105180066RK-09	South wall of Rooms 9 - 12	NAD
								2105180066RK-10	East wall of Breezeway	<1% chrysotile ^I
										1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-11	South wall of Rooms 6 - 8	NAD
								2105180066RK-12	East wall	NAD
								2105180066RK-13	North wall of Rooms 9 - 12	NAD
								2105180066RK-14	Southwest ceiling of Breezeway	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

^E G = Good; D = Damaged; SD = Severely Damaged

^F Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^G NOTE: 1) Wood overhangs. 2) No window putty.

^H NAD = No Asbestos Detected.

^I Sample 10 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the stucco is a non-regulated material.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^J	Type ^K	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Classroom Building (Rooms 13 thru 16)^L										
3	Stucco	Throughout exterior walls and breezeway ceiling	3,600 Square Feet	G	Surf.	No	<1	2105180066RK-15	West wall	<1% chrysotile ^M
										1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-16	South wall	NAD ^N
								2105180066RK-17	East wall	NAD
								2105180066RK-18	North wall	NAD
	Window putty	Throughout exterior side of select windows	40 Square Feet	G	Surf.	No	<1	2105180066RK-19	Northeast ceiling of Breezeway	<1% chrysotile
										1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-20	South wall of Rooms 13 - 15	<1% chrysotile ^O
										1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-21	South wall of Rooms 13 - 15	NAD
								2105180066RK-22	South wall of Room 16	<1% chrysotile
										1000-Pt. Ct.: <0.1% chrysotile

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only

^J G = Good; D = Damaged; SD = Severely Damaged

^K Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^L NOTE: 1) Wood overhangs. 2) No window putty.

^M Samples 15 and 17 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the stucco is a non-regulated material.

^N NAD = No Asbestos Detected.

^O Samples 20 and 22 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the window putty is a non-regulated material.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^P	Type ^Q	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Restroom Building^R										
4	Stucco	Throughout exterior walls and overhangs	1,600 Square Feet	G	Surf.	No	<1	2105180066RK-23	Southwest overhang at restroom entry	NAD ^S
								2105180066RK-24	West wall	NAD
								2105180066RK-25	South wall	NAD
								2105180066RK-26	East wall	NAD
								2105180066RK-27	North wall	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only

^P G = Good; D = Damaged; SD = Severely Damaged

^Q Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^R NOTE: 1) No window putty.

^S NAD = No Asbestos Detected.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^T	Type ^U	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Multi-Purpose Building^V										
5	Stucco	Throughout exterior walls and overhangs	6,000 Square Feet	G	Surf.	No	<1	2105180066RK-28	West wall	<1% chrysotile ^W 1000-Pt. Ct.: 0.1% chrysotile
								2105180066RK-29	South wall	<1% chrysotile 1000-Pt. Ct.: <0.1% chrysotile: NAD ^X
								2105180066RK-30	South overhang by Custodial Room	<1% chrysotile 1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-31	East wall, center	<1% chrysotile 1000-Pt. Ct.: 0.1% chrysotile
								2105180066RK-32	North wall	<1% chrysotile 1000-Pt. Ct.: <0.1% chrysotile

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

^T G = Good; D = Damaged; SD = Severely Damaged

^U Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^V NOTE: 1) No window putty.

^W Samples 28 thru 32 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the stucco is a non-regulated material.

^X NAD = No Asbestos Detected.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^y	Type ^z	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Multi-Purpose Building (continued)										
5	Stucco	Throughout exterior walls and overhangs						2105180066RK-33	East wall, north end	<1% chrysotile ^{AA}
										1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-34	East overhang	<1% chrysotile
										1000-Pt. Ct.: <0.1% chrysotile

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only

^y G = Good; D = Damaged; SD = Severely Damaged

^z Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^{AA} Samples 33 and 34 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the stucco is a non-regulated material.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^{BB}	Type ^{CC}	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Classroom Building (Rooms 33 thru 35)^{DD}										
6	Stucco	Throughout exterior walls and overhang	3,500 Square Feet	G	Surf.	No	0	2105180066RK-35	West wall	<1% chrysotile ^{EE} 1000-Pt. Ct.: <0.1% chrysotile
								2105180066RK-36	North wall	NAD ^{FF}
								2105180066RK-37	East wall	NAD
								2105180066RK-38	South wall	NAD
								2105180066RK-39	East overhang	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

^{BB} G = Good; D = Damaged; SD = Severely Damaged

^{CC} Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^{DD} NOTE: 1) No window putty.

^{EE} Sample 35 that had a result of less than 1% chrysotile via PLM analysis were further analyzed via the 1000-point count method. The analysis by 1000-point count analysis revealed that under Cal/OSHA regulations the stucco is a non-regulated material.

^{FF} NAD = No Asbestos Detected.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^{GG}	Type ^{HH}	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Classroom Building (Room 36) ^{II}										
7	Stucco	Throughout exterior walls and overhang	2,200 Square Feet	G	Surf.	No	0	2105180066RK-40	North wall	NAD ^{JJ}
								2105180066RK-41	East wall	NAD
								2105180066RK-42	South wall	NAD
								2105180066RK-43	West wall	NAD
								2105180066RK-44	East overhang	NAD
Portables ^{KK}										
8	Stucco	South wall at Room 32 ^{LL}	360 Square Feet	G	Surf.	No	0	2105180066RK-45	East end	Layers A & B: NAD
								2105180066RK-46	Center	Layers A & B: NAD
								2105180066RK-47	West end	Layers A & B: NAD
No suspect asbestos-containing materials were identified on the exterior walls of Portables 5, 17 thru 32 and Restroom Portable.										
Covered Walkways ^{MM}										
No suspect asbestos-containing materials were identified on the exterior walls of Southeast, Northeast and Northwest Covered Walkways.										

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

^{GG} G = Good; D = Damaged; SD = Severely Damaged

^{HH} Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^{II} NOTE: 1) No window putty.

^{JJ} NAD = No Asbestos Detected.

^{KK} NOTE: 1) Wood walls and overhangs of Portables 5, 17 thru 32, Restroom Portable. 2) No window putty of Portables 5, 17 thru 32, Restroom Portable.

^{LL} Portable 32 south wall has stucco other walls are wood.

^{MM} NOTE: 1) Wood ceilings.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition ^{NN}	Type ^{OO}	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Campus										
9	Asphalt paving	Parking Lot 1	20,000 Square Feet	G	Misc.	No	<1	2105240066RK-48	North	NAD ^{PP}
								2105240066RK-49	Northwest	NAD
								2105240066RK-50	Center-east	NAD
								2105240066RK-51	South-center	NAD
								2105240066RK-52	Southeast	NAD
10	Asphalt paving	Parking Lot 2	9,500 Square Feet	G	Misc.	No	<1	2105240066RK-53	West	NAD
								2105240066RK-54	Center-north	NAD
								2105240066RK-55	East	NAD
11	Asphalt paving	Kindergarten Playground	3,000 Square Feet	G	Misc.	No	<1	2105240066RK-56	West	NAD
								2105240066RK-57	Center	NAD
								2105240066RK-58	Northeast	NAD
12	Asphalt paving	Main Playground	30,000 Square Feet	G	Misc.	No	<1	2105250066RK-59	North of Room 13	NAD
								2105250066RK-60	Northwest of Room 16	NAD
								2105250066RK-61	Southeast	NAD
								2105250066RK-62	South of Room 15	NAD
								2105250066RK-63	Southwest	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only

^{NN} G = Good; D = Damaged; SD = Severely Damaged

^{OO} Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^{PP} NAD = No Asbestos Detected.

POLARIZED LIGHT MICROSCOPY (PLM) ANALYSIS DATA

Shuey Elementary School
8472 East Wells Street
Rosemead, California 91770

Homogeneous Material #	Material Description	Material Location	Estimated Quantity	Condition QQ	Type ^{RR}	Friable	Percent Damaged	Sample Number	Sample Location	Analytical Results
Campus										
13	Asphalt paving	South of Parking Lot 1 and South of Portables 22 thru 27	10,000 Square Feet	G	Misc.	No	<1	2105250066RK-64	South of Portable 22	NAD ^{SS}
								2105250066RK-65	South of Portables 26	NAD
								2105250066RK-66	South side of parking lot 1	NAD

Note: This table must be used in conjunction with the entire report. This document is not to be used for contract bidding and is intended to be used to identify asbestos-containing materials and their locations only.

The remainder of this page is blank.

^{QQ} G = Good; D = Damaged; SD = Severely Damaged

^{RR} Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation

^{SS} NAD = No Asbestos Detected.

IV. FINDINGS

EE conducted a limited asbestos inspection of the permanent buildings, portables and covered walkways at Shuey Elementary School located at 8472 East Wells Street, Rosemead, California.

Thirteen (13) homogeneous material groups were identified during the visual property inspection. Sixty-six (66) samples of suspect asbestos-containing materials were collected and delivered to AmeriSci of Carson, CA and LA Testing of South Pasadena for analysis. The homogeneous area and sampling results are listed on the table in Section III.

The analytical data revealed that the sampled materials do not contain asbestos.

V. CONCLUSIONS/RECOMMENDATIONS

No asbestos-containing material (ACM) was identified during this inspection. Activities involving the inspected material may proceed as normal construction actions. If suspect asbestos materials that were not sampled are to be disturbed, additional sampling will be required.

If you have any questions, please call Mr. Tim Galeana at 626-441-7050. We are glad we could be of service to you.

VI. DISCLAIMER/REPORT LIMITATIONS

All reports and recommendations are based on conditions and practices observed and information made available to Executive Environmental (EE) by the client and the designated sites/facilities on the days sampling was conducted. This report does not purport to set forth all hazards, nor to indicate that other hazards do not exist. No responsibility is assumed by EE for the control or correction of conditions or practices existing at the facilities, or at any other premises surveyed by EE, for and on the behalf of the client. Services provided by EE shall be governed by the standard of practice for professional services measured at the time those services are rendered.

All information contained in this report is proprietary and limited to the scope of services, parameters of the analytical methods used and the conditions present at the time of this inspection. Any references to quantities are considered estimates and are not to be construed as actual.

APPENDIX A – LABORATORY ANALYSIS REPORT



Please Reply To:

AmeriSci Los Angeles

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

FACSIMILE TELECOPY TRANSMISSION

To: Yesenia Galeana	From: Thu M. Nguyen
Executive Environmental Services Corporation	AmeriSci Job #: 921051339
Fax #:	Subject: PLM 3 day Results
	Client Project: 21-Z0046-0066; Admin and Rooms
	1-4, Rooms 6-12, Rooms 13-26,
	Restroom Building,
Email: info@execenv.com,ygaleana@execenv.com	

Date: Saturday, May 22, 2021

Time: 07:21:56

Number of Pages: _____

(including cover sheet)

Comments:

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

Certified Analysis Service 24 Hours A Day • 7 Days A Week Competitive Prices
visit our web site - www.amerisci.com

Boston • Los Angeles • New York • Richmond

**AmeriSci Los Angeles**

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

PLM Bulk Asbestos Report

Executive Environmental Services Corpo **Date Received** 05/18/21 **AmeriSci Job #** 921051339
Attn: Yesenia Galeana **Date Examined** 05/20/21 **P.O. #**
310 East Foothill Blvd. **Page** 1 of 8
Suite 200 **RE: 21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms**
Arcadia, CA 91006 **13-26, Restroom Building, MPR, Rooms 33-35, Room 36**

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 01 01 Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Breezeway Ceiling	921051339-01	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 02 01 Location: Exterior, South Wall Of Admin / Exterior Stucco	921051339-02	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 03 01 Location: Exterior, South Wall Of Rooms 1-2 / Exterior Stucco	921051339-03	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 04 01 Location: Exterior, East Wall / Exterior Stucco	921051339-04	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 05 01 Location: Exterior, North Wall Of Admin / Exterior Stucco	921051339-05	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 06 01	921051339-06	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 07 01	921051339-07	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 08 02	921051339-08	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 09 02	921051339-09	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 10 02	921051339-10	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Tan/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 11 02	921051339-11	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms 13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 12 02	921051339-12 Location: Exterior, East Wall / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 13 02	921051339-13 Location: Exterior, North Wall of Rooms 9-12 / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 14 02	921051339-14 Location: Exterior, SW Ceiling Of Breezeway / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/20/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 15 03	921051339-15 Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Breezeway Ceiling	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Tan/Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 16 03	921051339-16 Location: Exterior, South Wall / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 17 03	921051339-17 Location: Exterior, East Wall / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms 13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 18 03	921051339-18 Location: Exterior, North Wall / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 19 03	921051339-19 Location: Exterior, NE Ceiling Of Breezeway / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Tan/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 20 04	921051339-20 Location: Exterior, South Wall Of Rooms 13-15 / Exterior Window Putty / T-O Select Exterior Windows	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Tan/Beige, Heterogeneous, Fibrous, Window Putty Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 21 04	921051339-21 Location: Exterior, South Wall Of Rooms 13-15 / Exterior Window Putty	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Beige, Heterogeneous, Non-Fibrous, Window Putty Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 22 04	921051339-22 Location: Exterior, South Wall Of Room 16 / Exterior Window Putty	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Tan/Beige, Heterogeneous, Fibrous, Window Putty Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 23 05	921051339-23 Location: Exterior, SW Overhang At RR Entry / Exterior Stucco	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 24 05 Location: Exterior, West Wall / Exterior Stucco	921051339-24	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 25 05 Location: Exterior, South Wall / Exterior Stucco	921051339-25	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 26 05 Location: Exterior, East Wall / Exterior Stucco	921051339-26	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 27 05 Location: Exterior, North Wall / Exterior Stucco	921051339-27	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 28 06 Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Overhangs	921051339-28	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 29 06 Location: Exterior, South Wall / Exterior Stucco	921051339-29	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms 13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 30 06	921051339-30 Location: Exterior, South Overhang By Custodial Room / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 31 06	921051339-31 Location: Exterior, East Wall - Center / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 32 06	921051339-32 Location: Exterior, North Wall / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 33 06	921051339-33 Location: Exterior, East Wall - North End / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 34 06	921051339-34 Location: Exterior, East Overhang / Exterior Stucco	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			
2105180066RK - 35 07	921051339-35 Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Overhang	Yes	Trace (<1 %) (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <1. % Other Material: Non-fibrous 100 %			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 36 07 Location: Exterior, North Wall / Exterior Stucco	921051339-36	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 37 07 Location: Exterior, East Wall / Exterior Stucco	921051339-37	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 38 07 Location: Exterior, South Wall / Exterior Stucco	921051339-38	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 39 07 Location: Exterior, East Overhang / Exterior Stucco	921051339-39	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 40 08 Location: Exterior, North Wall / Exterior Stucco / T-O Exterior Walls And Overhang	921051339-40	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 41 08 Location: Exterior, East Wall / Exterior Stucco	921051339-41	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			


Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 42 08 Location: Exterior, South Wall / Exterior Stucco	921051339-42	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 43 08 Location: Exterior, West Wall / Exterior Stucco	921051339-43	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			
2105180066RK - 44 08 Location: Exterior, East Overhang / Exterior Stucco	921051339-44	No	NAD (by CVES) by Thu M. Nguyen on 05/21/21
Analyst Description: White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-fibrous 100 %			

Reporting Notes:

Analyzed By: Thu M. Nguyen ; Date Analyzed: 5/20/2021 5.20.21
 *NAD = no asbestos detected; Detection Limit < 1%; Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; NA = not analyzed; NA/PS = not analyzed / positive stop; NVA = No Visible Asbestos; PLM (polarized light microscopy) Bulk Asbestos Analysis by EPA 600/R-93/116, including requirements for EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200346-0); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full with the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

021051339



Industrial Hygiene Laboratory Submittal
Asbestos -- PLM

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

☐ Routine (5 Days) ☐ RUSH (surcharges may apply) Circle 6 24 48 3 to 5 hours hours hours days

Project #: 21-Z0046-0066 **Sampled by:** Rhys Kuzmic **Site Zip Code:** 91770 **Sample Date:** 05/18/2021 **Page** 1 **of** 7

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Building Name: Admin and Rooms L-4

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@excecenv.com ☒ Other: ygaleana@excecenv.com
☒ US Mail Report to: ☒ Originating office check marked above ☐ Other: ☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-01	Exterior, West Wall	Exterior stucco	No exterior walls and breezeway ceiling	1	6,000 sq ft	CL
-02	Exterior, south wall of Admin					
-03	Exterior, south wall of Rooms 1-2					
-04	Exterior, east wall					
-05	Exterior, north wall of Admin					
-06	Exterior, west wall of breezeway					
-07	Exterior, SW ceiling of breezeway					

Prefix: 2105180066RKH

Notes: (R)un Ken 05/18/2021 2:00PM

Received By, Date, & Time: By, Date, & Time:

92051339



Industrial Hygiene Laboratory Submittal
Asbestos -- PLM

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

☐ Routine (5 Days) ☒ RUSH (surcharges may apply) Circle 6 24 48 3 to 5 hours hours hours days

Project #: 21-Z0046-0066 **Sampled by:** Rhys Kuzmic

Site Zip Code: 91770 **Sample Date:** 05/18/2021 **Page 2 of 7**

Building Name: Rooms 6-12

The receiving Laboratory is required to complete the following:

1. All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
2. Analyze all samples by PLM by EPA 600/R-93/116.
3. Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygalearna@execenv.com

☒ US Mail Report to: ☒ Originating office check marked above ☐ Other: ☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-08	Exterior, west wall	Exterior stucco	Exterior walls, overhangs and breezeway ceiling	2	5,000 SF	<1
-09	Exterior, south wall of Rooms 9-12					
-10	Exterior, east wall of breezeway					
-11	Exterior, south wall of Rooms 6-8					
-12	Exterior, east wall					
-13	Exterior, north wall of Rooms 9-12					
-14	Exterior, SW ceiling of breezeway					

Prefix: 2105180066RK

Notes:

Received By, Date, & Time: 05/18/2021 2:00 PM

Received By, Date, & Time: 05/18/2021 1400

Rev. 1/19 ©Copyright 2019 All Rights Reserved Form: AL-006PLM

921051339



Industrial Hygiene Laboratory Submittal
Asbestos -- PLM

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

<input type="checkbox"/> Routine (5 Days) <input type="checkbox"/> RUSH (surcharges may apply) Circle 6 24 48 3 to 5 One hours hours days	Project #: 21-Z0046-0066	Sampled by: Rhys Kuzmic	Site Zip Code: 91770	Sample Date: 05/18/2021	Page 3 of 7
--	------------------------------------	-----------------------------------	--------------------------------	-----------------------------------	--------------------

Building Name: Rooms 13-26

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygaleana@execenv.com;
☒ US Mail Report to: ☒ Originating office check marked above ☐ Other:
☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-15	Exterior, West Wall	Exterior stucco	To exterior walls and breezeway ceilings	3	3,600 SF	<1
-16	Exterior, south wall					
-17	Exterior, east wall					
-18	Exterior, north wall					
-19	Exterior, NE ceiling of breezeway					
-20	Exterior, south wall of Rooms 13-15	Exterior window putty	To select exterior windows	4	40 SF	<1
-21	Exterior, south wall of Rooms 13-15					
-22	Exterior, south wall of Room 16					

Prefix: 2105180066RK

Notes:

Released By, Date, & Time:	Received By, Date, & Time:
Released By, Date, & Time:	Received By, Date, & Time:

By Date, & Time: 05/18/2021 2:00 PM

By Date, & Time: 05/18/2021 1:00 PM

921051339



Industrial Hygiene Laboratory Submittal Asbestos -- PLM

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

<input type="checkbox"/> Routine (5 Days)	<input type="checkbox"/> RUSH (surcharges may apply) Circle 6 24 48 3 to 5 One hours hours days	Project #: 21-Z0046-0066	Sampled by: Rhys Kuzmic	Site Zip Code: 91770	Sample Date: 05/18/2021	Page 4 of 7
--	---	------------------------------------	-----------------------------------	--------------------------------	-----------------------------------	---------------------------

Building Name: Restroom Building

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygaleana@execenv.com

☒ US Mail Report to: ☒ Originating office check marked above ☐ Other: ☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-23	Exterior, SW overhang at per entry	Exterior stucco	To exterior walls and overhangs	5	1,600 SF	<1
-24	Exterior, West Wall					
-25	Exterior, South Wall					
-26	Exterior, east Wall					
-27	Exterior, north Wall					


Prefix: 2105180066RK

Notes:

Released By, Date, & Time:	Received By, Date, & Time:
<u>Rhys Kuz 05/18/2021 2:00PM</u>	<u>Proj 5/18/21 1400</u>

Rev. 1/19 ©Copyright 2019 All Rights Reserved Form: AL-006PLM

92051839



EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Industrial Hygiene Laboratory Submittal
Asbestos -- PLM

☐ Routine (5 Days)
☐ RUSH (surcharges may apply)
Circle 6 24 48 hours hours days

Project #: 21-Z0046-0066

Sampled by: Rhys Kuzmic

Site Zip Code: 91770

Building Name: MPR

Sample Date: 05/18/2021

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Alternate billing address: ygaleana@execenv.com

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-28	Exterior, West Wall	Exterior stucco	Exterior walls and overhangs	6	6,000 SF	<1
-29	Exterior, south wall					
-30	Exterior, south overhang by Catalina train					
-31	Exterior, east wall - center					
-32	Exterior, north wall					
-33	Exterior, east wall - north end					
-34	Exterior, east overhang					

Prefix: 2105180066 RK

Notes:

Released By, Date: 05/18/2021 2:00pm


Received By, Date: 5/18/21 1400

Released By, Date: & Time:

Released By, Date: & Time:

Rev. 1/19 ©Copyright 2019 All Rights Reserved Form: AL-006PLM

921051339

**EXECUTIVE ENVIRONMENTAL**
HEALTH & SAFETY SIMPLIFIED

Industrial Hygiene Laboratory Submittal
Asbestos -- PLM

Originating Office
☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:
☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

☐ Routine
(5 Days)
Circle 6 hours 24 hours 48 hours 3 to 5 days

☐ RUSH (surcharges may apply)
One day

Project #:
21-Z0046-0066

Sampled by:
Rhys Kuzmic

Site Zip Code:
91770

Sample Date:
05/18/2021

Building Name: Rooms 33-35

Page 6 of 7

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygaleana@execenv.com;
☒ US Mail Report to: ☒ Originating office check marked above ☐ Other:
☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-35	Exterior west wall	Exterior stucco	TO exterior walls and overhang	7	3,500 SF	0
-36	Exterior north wall					
-37	Exterior east wall					
-38	Exterior south wall					
-39	Exterior east overhang					

Prefix: 2105180066RK

Notes:

Received By Date & Time: 05/18/2021 2:00 PM

Received By Date & Time: 5/18/21 1400

Released By Date & Time:

Released By Date & Time:

Rev. 1/19

©Copyright 2019 All Rights Reserved

Form: AL-006PLM

921051339



Industrial Hygiene Laboratory Submittal

Asbestos -- PLM

☐ Routine
(5 Days)

☐ RUSH (surcharges may apply)
Circle 6 24 48 hours hours days

Originating Office

☒ 310 E. Foothill Blvd., Suite 200
Arcadia, CA 91006
Phone: 626.441.7050
Fax: 626.441.0016

Lab Submitted to:

☒ AmeriSci
☐ EMLab (Glendale)
☐ LA Testing

Project #:

21-Z0046-0066

Sampled by:

Rhys Kuzmic

Site Zip Code:

91770

Sample Date:

05/18/2021

Page 7 of 7

Building Name: Room 36

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygalearna@execenv.com;
☒ US Mail Report to: ☒ Originating office check marked above ☐ Other:
☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-40	Extens, North Wall	Extens stucco	T-O extens walls and overhang	8	2,200 SF	0
-41	Extens, east wall					
-42	Extens, south wall					
-43	Extens, west wall					
-44	Extens, east overhang					

Notes:

Released By, Date, & Time:

Rhys Kuzmic 05/18/2021 2:00PM

Received By, Date, & Time:

By 5/18/21 1400

Released By, Date, & Time:

By, Date, & Time:

Rev. 1/19

©Copyright 2019 All Rights Reserved

Form: AL-006PLM



Please Reply To:

AmeriSci Los Angeles

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

FACSIMILE TELECOPY TRANSMISSION

To: Yesenia Galeana
Executive Environmental Services Corporation
Fax #:
Email: info@execenv.com, ygaleana@execenv.com

From: Rosa E. Pena
AmeriSci Job #: 921051502
Subject: PLM 1000 point count 3 day Result
Client Project: 21-Z0046-0066; Admin and Rooms
1-4, Rooms 6-12, Rooms 13-26,
Restroom Building,

Date: Thursday, June 24, 2021

Time: 17:42:49

Comments:

Number of Pages: _____

(including cover sheet)

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

Certified Analysis

Service 24 Hours A Day • 7 Days A Week

Competitive Prices

visit our web site - www.amerisci.com

Boston • Los Angeles • New York • Richmond

**AmeriSci Los Angeles**

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

PLM Bulk Asbestos Report

Executive Environmental Services Corpo
Attn: Yesenia Galeana
310 East Foothill Blvd.
Suite 200
Arcadia, CA 91006

Date Received 05/25/21**Date Examined** 05/28/21**AmeriSci Job #** 921051502**P.O. #****Page** 1 of 3

RE: 21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36
(Report Amended 6/24/2021)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 15 03	921051502-01	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Breezeway Ceiling (Stop At First Positive)			
Analyst Description: Tan/Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco			
Asbestos Types: Chrysotile <0.1 % pc			
Other Material: Non-Asbestos/Inert 41.5 %			
Comment: Heat Sensitive (organic): 20.3%; Acid Soluble (inorganic): 38.2%; Inert (Non-asbestos): 41.5%			
2105180066RK - 19 03	921051502-02	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, NE Ceiling Of Breezeway / Exterior Stucco (Stop At First Positive)			
Analyst Description: Tan/Grey, Heterogeneous, Fibrous, Cementitious, Stucco			
Asbestos Types: Chrysotile <0.1 % pc			
Other Material: Non-Asbestos/Inert 67.3 %			
Comment: Heat Sensitive (organic): 15.9%; Acid Soluble (inorganic): 16.8%; Inert (Non-asbestos): 67.3%			
2105180066RK - 20 04	921051502-03	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, South Wall Of Rooms 13-15 / Exterior Window Putty / T-O Select Exterior Windows (Stop At First Positive)			
Analyst Description: Tan/Beige, Heterogeneous, Fibrous, Window Putty			
Asbestos Types: Chrysotile <0.1 % pc			
Other Material: Non-Asbestos/Inert 9.3 %			
Comment: Heat Sensitive (organic): 12.4%; Acid Soluble (inorganic): 78.3%; Inert (Non-asbestos): 9.3%			
2105180066RK - 22 04	921051502-04	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, South Wall Of Room 16 / Exterior Window Putty (Stop At First Positive)			
Analyst Description: Tan/Beige, Heterogeneous, Fibrous, Window Putty			
Asbestos Types: Chrysotile <0.1 % pc			
Other Material: Non-Asbestos/Inert 10.3 %			
Comment: Heat Sensitive (organic): 10.9%; Acid Soluble (inorganic): 78.8%; Inert (Non-asbestos): 10.3%			

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36
(Report Amended 6/24/2021)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 28 06	921051502-05	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Thu M. Nguyen on 06/24/21
Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Overhangs (Stop At First Positive)			
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 68 % Comment: Heat Sensitive (organic): 4.4%; Acid Soluble (inorganic): 27.6%; Inert (Non-asbestos): 68.0%			
2105180066RK - 29 06	921051502-06	No	NAD ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, South Wall / Exterior Stucco (Stop At First Positive)			
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Other Material: Non-Asbestos/Inert 63.6 % Comment: Heat Sensitive (organic): 9.1%; Acid Soluble (inorganic): 27.3%; Inert (Non-asbestos): 63.6%			
2105180066RK - 30 06	921051502-07	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, South Overhang By Custodial Room / Exterior Stucco (Stop At First Positive)			
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 67.4 % Comment: Heat Sensitive (organic): 9.5%; Acid Soluble (inorganic): 23.1%; Inert (Non-asbestos): 67.4%			
2105180066RK - 31 06	921051502-08	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Thu M. Nguyen on 06/24/21
Location: Exterior, East Wall - Center / Exterior Stucco (Stop At First Positive)			
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 66.4 % Comment: Heat Sensitive (organic): 2.9%; Acid Soluble (inorganic): 30.6%; Inert (Non-asbestos): 66.4%			
2105180066RK - 32 06	921051502-09	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, North Wall / Exterior Stucco (Stop At First Positive)			
Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 65.8 % Comment: Heat Sensitive (organic): 6.7%; Acid Soluble (inorganic): 27.5%; Inert (Non-asbestos): 65.8%			

PLM Bulk Asbestos Report

21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
13-26, Restroom Building, MPR, Rooms 33-35, Room 36
(Report Amended 6/24/2021)

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 33 06	921051502-10	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, East Wall - North End / Exterior Stucco (Stop At First Positive) Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 69.2 % Comment: Heat Sensitive (organic): 6.8%; Acid Soluble (inorganic): 24.0%; Inert (Non-asbestos): 69.2%			
2105180066RK - 34 06	921051502-11	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, East Overhang / Exterior Stucco (Stop At First Positive) Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 70.4 % Comment: Heat Sensitive (organic): 7.0%; Acid Soluble (inorganic): 22.6%; Inert (Non-asbestos): 70.4%			
2105180066RK - 35 07	921051502-12	Yes	Trace (<0.1 % pc) ¹ (by 1000 pt ct) by Rosa E. Pena on 05/28/21
Location: Exterior, West Wall / Exterior Stucco / T-O Exterior Walls And Overhang Analyst Description: Beige/Grey, Heterogeneous, Fibrous, Cementitious, Stucco Asbestos Types: Chrysotile <0.1 % pc Other Material: Non-Asbestos/Inert 63.2 % Comment: Heat Sensitive (organic): 4.1%; Acid Soluble (inorganic): 32.7%; Inert (Non-asbestos): 63.2%			

Reporting Notes:

(1) EPA 1000 Point Count Analysis performed on inert residue remaining after 480C heat and HCl acid treatments.

Analyzed By: Rosa E. Pena ; Date Analyzed: 5/28/2021 6/24/21

*NAD = no asbestos detected; Detection Limit <1%; Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; NA = not analyzed; NA/PS = not analyzed / positive stop; NVA = No Visible Asbestos; PLM (polarized light microscopy) Bulk Asbestos Analysis by EPA 600/R-93/116, including requirements for EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200346-0); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full with the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: 



Please Reply To:

AmeriSci Los Angeles

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

FACSIMILE TELECOPY TRANSMISSION

To: Yesenia Galeana	From: Madeline Cumad
Executive Environmental Services Corporation	AmeriSci Job #: 921061723
Fax #:	Subject: PLM 1000 point count 5 day Result
	Client Project: 21-Z0046-0066; Admin and Rooms
	1-4, Rooms 6-12, Rooms 13-26,
	Restroom Building,
Email: info@execenv.com,ygaleana@execenv.com	

Date: Wednesday, June 23, 2021

Time: 06:34:24

Comments:

Number of Pages:

8

(including cover sheet)

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

Certified Analysis Service 24 Hours A Day • 7 Days A Week Competitive Prices
visit our web site - www.amerisci.com

Boston • Los Angeles • New York • Richmond

**AmeriSci Los Angeles**

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

PLM Bulk Asbestos Report

Executive Environmental Services Corpo **Date Received** 06/17/21 **AmeriSci Job #** 921061723
Attn: Yesenia Galeana **Date Examined** 06/23/21 **P.O. #**
310 East Foothill Blvd. **Page** 1 **of** 1
Suite 200 **RE:** 21-Z0046-0066; Admin and Rooms 1-4, Rooms 6-12, Rooms
Arcadia, CA 91006 13-26, Restroom Building, MPR, Rooms 33-35, Room 36

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2105180066RK - 10	921061723-01	Yes	Trace (<0.1 % pc) ¹
Location: Exterior, East Wall Of Breezeway / Exterior Stucco			(by 1000 pt ct)
			by Madeline Cumad
			on 06/23/21
Analyst Description: Tan/Grey, Heterogeneous, Non-Fibrous, Cementitious, Stucco			
Asbestos Types: Chrysotile <0.1 % pc			
Other Material: Non-Asbestos/Inert 48.6 %			
Comment: Heat Sensitive (organic): 9.1%; Acid Soluble (inorganic): 42.2%; Inert (Non-asbestos): 48.6%			

Reporting Notes:

(1) EPA 1000 Point Count Analysis performed on inert residue remaining after 480C heat and HCl acid treatments.

Analyzed By: Madeline Cumad ; Date Analyzed: 6/23/2021 6-23-21

*NAD = no asbestos detected; Detection Limit <1%; Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; NA = not analyzed; NA/PS = not analyzed / positive stop; NVA = No Visible Asbestos; PLM (polarized light microscopy) Bulk Asbestos Analysis by EPA 600/R-93/116, including requirements for EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200346-0); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full with the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: 



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322109897

Customer ID: 32EXEC52

Customer PO:

Project ID:

Attention: Yesenia Galeana
Executive Environmental Services Corp.
310 East Foothill Blvd.
Suite 200
Arcadia, CA 91006

Project: 21-Z0046-0066 / Sampler: Rhys Kuzmic

Phone: (626) 441-7050

Fax: (626) 441-0016

Received Date: 05/25/2021 3:15 PM

Analysis Date: 05/27/2021 - 05/28/2021

Collected Date: 05/24/2021

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Appearance	Non-Asbestos		Asbestos % Type
		% Fibrous	% Non-Fibrous	
2105240066RK-45-A <small>322109897-0001</small>	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-45-B <small>322109897-0001A</small>	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-46-A <small>322109897-0002</small>	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-46-B <small>322109897-0002A</small>	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-47-A <small>322109897-0003</small>	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-47-B <small>322109897-0003A</small>	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-48 <small>322109897-0004</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-49 <small>322109897-0005</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-50 <small>322109897-0006</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-51 <small>322109897-0007</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-52 <small>322109897-0008</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-53 <small>322109897-0009</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-54 <small>322109897-0010</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-55 <small>322109897-0011</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-56 <small>322109897-0012</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-57 <small>322109897-0013</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 05/28/2021 09:53:53



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322109897

Customer ID: 32EXEC52

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Appearance	Non-Asbestos		Asbestos % Type
		% Fibrous	% Non-Fibrous	
2105240066RK-58 <small>322109897-0014</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-59 <small>322109897-0015</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-60 <small>322109897-0016</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-61 <small>322109897-0017</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-62 <small>322109897-0018</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-63 <small>322109897-0019</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-64 <small>322109897-0020</small>	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-65 <small>322109897-0021</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2105240066RK-66 <small>322109897-0022</small>	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)

Humberto Espinoza Bajo (9)


Joel Paruli (16)

Jerry Drapala Ph.D, Laboratory Manager
or Other Approved Signatory

LA Testing maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by LA Testing. LA Testing bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore LA Testing recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by LA Testing South Pasadena, CA NVLAP Lab Code 200232-0, CA ELAP 2283

Initial report from: 05/28/2021 09:53:53



<input type="checkbox"/> Routine (5 Working Days)	<input type="checkbox"/> RUSH (surcharges may apply) Circle 6 24 48 One hours hours hours 3 to 5 days	Project #: 21-Z0046-0066
--	--	-----------------------------

The receiving Laboratory is required to complete the following:

The receiving Laboratory is required to complete the following:

1. All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 **with** a copy of the lab report.
2. Analyze all samples by PLM by EPA 600/R-93/116.
3. Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%
4. All lab reports and invoices are to contain the Project Number from above.
5. Unsigned and reports marked draft are unacceptable.
6. Report to the attention of: Yesenia Galeana, Phone: (562) 889-1327

☒ Optional Items to be completed by the laboratory (if check marked):

☒ US Mail Report to: ☒ Originating office check marked above ☐ Other: ☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-415	Room 32, south wall - east end	Exterior stucco	Room 32 south wall corner walls are wood's	9	360 SF	0
-416	Room 32, south wall - center	↓		↓	↓	↓
-417	Room 32, south wall - west end					

Prefix: 2105240066RK

Notes:


Released
By, Date,
& Time:

2025/2026 3:15 PM

Received
By, Date,
& Time::

24WD S/S/21 S/S/21

Released
By, Date,
& Time:

Page 2 Of 5

Notes:

Rev. 1/19

#322109897



Industrial Hygiene Laboratory Submittal Asbestos -- PLM

☐ Routine
(5 Days)

☐ RUSH (surcharges may apply)
Circle 6 24 48 hours hours days

Project #: 21-Z0046-0066

Sampled by: Rhys Kuzmic

Site Zip Code: 91770

Sample Date: 05/24/2021

Page 10 of 12

The receiving Laboratory is required to complete the following:

1. All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
2. Analyze all samples by PLM by EPA 600/R-93/116.
3. Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%

Building Name: Campinos

4. All lab reports and invoices are to contain the Project Number from above.
5. Unsigned and reports marked draft are unacceptable.
6. Report to the attention of: Yessenia Galeana, Phone: (562) 889-1327

Optional Items to be completed by the laboratory (if check marked): ☒ Email Report to: Info@execenv.com ☒ Other: ygaaleana@execenv.com;

☒ US Mail Report to: ☒ Originating office check marked above ☐ Other: ☐ Alternate billing address:

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-53	Parking Lot 2, west	Asphalt paving	Parking Lot 2	11	9,500 SF	<1
-54	Parking Lot 2, center-North	↓	↓	↓	↓	↓
-55	Parking Lot 2, east	↓	↓	↓	↓	↓
-56	Kindergarten Playground, west	Asphalt paving	Kindergarten Playground	12	3,000 SF	<1
-57	Kindergarten Playground, center	↓	↓	↓	↓	↓
-58	Kindergarten Playground, NE	↓	↓	↓	↓	↓


Prefix: 21052400667K

Notes:

Released By, Date, & Time: Rm Yaw 05/25/2021 3:15PM

Received By, Date, & Time: RP 5/25/21 3:15pm


Released By, Date, & Time:



Sample Date: 05/25/2021

Prefix: 2105250066RK

Form: AI -006P1 M



The receiving Laboratory is required to complete the following:

1. All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
2. Analyze all samples by PLM by EPA 600/R-93/116.
3. Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%
4. All lab reports and invoices are to contain the Project Number from above.
5. Unsigned and reports marked draft are unacceptable.
6. Report to the attention of: Yesenia Galeana, Phone: (562) 889-1327

Optional Items to be completed by the laboratory (if check marked): ☒

Email Report to: ☒ Info@execenv.com ☒ Other: ygaleana@execenv.com;

☒ US Mail Report to: ☒ Originating office check marked above ☐ Other:

☐ Alternate billing address:

[illegible]

Prefix: 2105250666RK

Notes:


Released By, Date, & Time:	12/21/50 WDR:c WDR	Received By, Date, & Time:
----------------------------------	--------------------------	----------------------------------

RD 5/25/21 3:15pm

Released
By, Date,
& Time:

APPENDIX B – SAMPLE LOCATIONS DRAWINGS

Shuey Elementary School



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: Site Map



EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Administration/Classroom Building
(Rooms 1-4)



○ - PLM Sample Location



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: PLM Sample Location




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Classroom Building
(Rooms 6-12)



○ - PLM Sample Location



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: PLM Sample Location




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Classroom Building (Rooms 13-16)



○ - PLM Sample Location



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: PLM Sample Location




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Restroom Building



Client: Rosemead SD

Project#: 21-10046-0066

Info: PLM Sample Location




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey ES - Painting Project
Address: 3720 Rio Hondo Avenue
Rosemead, CA 91770

Drawing Not to Scale - © 2012

Multi-Purpose Building



Client: Rosemead School District

Project #: 21-Z046-0066

Info: PLM Sample Location





EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School
8471 Wells Street
Address: Rosemead, CA 91770

Drawing Not to Scale - © 2012

Classroom Buildings (Room 33-35)



○ - PLM Sample Location



Client: Rosemead SD

Project#: 21-10046-0066

Info: PLM Sample Location





EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey ES - Painting Project
Address: 3720 Rio Hondo Avenue
Rosemead, CA 91770

Drawing Not to Scale - © 2012

Portables
Exterior



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: No Suspect Material Identified




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Portables
(Rooms 22-27) and Restroom



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: No Suspect Material Identified



EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

Portables (Rooms 28-30)

Room
28

Room
29

Room
30



Client: Rosemead SD

Project#: 21-10046-0066

Info: No Suspect Material Identified




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey ES - Painting Project
Address: 3720 Rio Hondo Avenue
Rosemead, CA 91770

Drawing Not to Scale - © 2012

Portables (Rooms 31-32)



○ - PLM Sample Location



Client: Rosemead SD

Project#: 21-10046-0066

Info: PLM Sample Location




EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey ES - Painting Project
Address: 3720 Rio Hondo Avenue
Rosemead, CA 91770

Drawing Not to Scale - © 2012

Covered Walkways/Campus



Client: Rosemead School District

Project #: 21-Z0046-0066

Info: PLM Sample Location



EXECUTIVE ENVIRONMENTAL
HEALTH & SAFETY SIMPLIFIED

Site: Shuey Elementary School-Painting Project
Address: 8472 East Wells Street
Rosemead, California 91770

Drawing Not to Scale - © 2012

APPENDIX C – STAFF CERTIFICATION

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Rhys D Kuzmic

Name

Certification No. **09-4586**

Expires on **01/20/22**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

